

Außen-Schnelltaster mit Uhr




- 1 fester und 1 beweglicher Tastarm
- mit HM-Messkugeln
- zum Messen von Bohrungen und Innennuten
- inkl. Kunststoffetui

Caliper gauge for outside measurements

- 1 fixed and 1 movable arm
- with carbide measuring balls
- for the measurement of grooves and bores
- incl. plastic case



270-002

> mm <	 mm	 mm	 mm	T Ø mm	No.
0-20	0,01	0,03	80	1,5	270-000
10-30	0,01	0,03	80	1,5	270-001
20-40	0,01	0,03	80	1,5	270-002
30-50	0,01	0,03	80	1,5	270-003
40-60	0,01	0,03	80	1,5	270-004

Außen-Schnelltaster digital




- 1 fester und 1 beweglicher Tastarm
- mit HM-Messkugeln
- großes Display mit 170° Rotation
- Absolut- und Relativ-Messung, mm/inch, Toleranzmessung, Umstellung Ziffernschrittwert
- zum Messen von Bohrungen und Innennuten
- inkl. Kunststoffetui



Digital caliper gauge for outside measurements

- 1 fixed and 1 movable arm
- with carbide measuring balls
- large display, 170° rotatable
- absolute/relative measurement, mm/inch, tolerance measurement, switch of digit step value
- for the measurement of grooves and bores
- incl. plastic case



270-012

> mm <	 mm	 mm	 mm	T Ø mm	No.
0-20	0,005	0,03	80	1,5	270-010
10-30	0,005	0,03	80	1,5	270-011
20-40	0,005	0,03	80	1,5	270-012
30-50	0,005	0,03	80	1,5	270-013
40-60	0,005	0,03	80	1,5	270-014

> mm <	Messbereich	Range
	Ableseung	Reading
	Genauigkeit	Accuracy
T	HM-Tastkugel	Carbide ball
U	Bügeltiefe	Depth of frame